## This Page Is Inserted by IFW Operations and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
  - FADED TEXT
  - ILLEGIBLE TEXT
  - SKEWED/SLANTED IMAGES
  - COLORED PHOTOS
  - BLACK OR VERY BLACK AND WHITE DARK PHOTOS
  - GRAY SCALE DOCUMENTS

## IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.

## MULTI-CHANNEL DIGITAL VIDEO SIGNAL 184




FIG. 1A

FIG. 18




FIG. 2A




FIG. 2B




FIG 3A




FIG 3B





FIG 3C



Deallocate cached data for Y

FVCs that are not being cached (assume that is


**FVC 7)** 


Reassign tuner from Y to FVC 7

Start caching data for FVC 7

Continue caching FVC 2

FIG. 4A








FIG. 5